

1 Building the PDM: Instructions


In your kits for the Portable Partial Derivative Machine should be the following:

- A 1ft by 1ft board with 5 holes and measuring tapes (the measuring tapes will be on the **top** side)
- 2 S-hooks
- A spring with 3 strings attached
- 2 small cloth bags
- 4 large ball bearings
- 8 small ball bearings
- 2 vertical clamp pulleys
- A ziploc bag containing
 - 5 screws
 - 5 hex nuts
 - 5 washers
 - 5 wing nuts
 - 2 horizontal pulleys

To assemble the Portable PDM, start by placing the PDM on a table surface with the measuring tapes perpendicular to the table's edge and the board edge with 3 holes closest to you.

- (a) one screw should be put through each hole so that the threads stick out through the top side of the board. Next use a hex nut to secure **each** screw in place. It is not critical that they be screwed on any more than you can comfortably manage by hand.
- (b) After securing all 5 screws in place with a hex nut, put a washer on each screw.
- (c) Slide a horizontal pulley onto screws 1 and 2 (as labeled above).
- (d) On all 5 screws, add a wing nut to secure the other pieces. Again, it does not need to be tightened all the way as long as it is secure enough that nothing will fall off.
- (e) Using the middle wingnut/washer/screw (Screw 4), clamp the shortest of the strings tied to the spring.
- (f) Loop the remaining 2 looped-ends of string around the horizontal pulleys and along the measuring tape.

Building the PDM: Instructions



- (g) Using the string as a guide, clamp the vertical pulleys into place on the edge of the board.
- (h) Through the looped-end of each string, place 1 S-hook.
- (i) Put the other end of each s-hook through the hole in the small cloth bag.

Here is a poor photo of the final result, which doesn't show the two vertical pulleys. If you would like, you could view a video of the building process.

